

# CAD-CUT® UltraWeed™ Heat Transfer Vinyl

## Application Instructions

### 1-Color Application Instructions

**Time:**

12 seconds

**Temperature:**

260-300°F

**Pressure:**

Medium

**Peel:**

Hot

### 2-Color Application Instructions

**Time:**

Press background layer for 2-3 seconds, place foreground layer for full application of 12 seconds

**Temperature:**

260-300°F

**Pressure:**

Medium

**Peel:**

Hot

### Hotronix® 360 IQ™ Hat Press

**Time:**

45 seconds

**Upper:**

280°F

**Lower:**

320°F

**Pressure:**

Medium

**Peel:**

Warm/Cold

**Cover Sheet:**

1/8" Foam Pad

### Special Notes

If the garment is 50% or more cotton it will require 280°F + degrees.

### Care Instructions

Machine wash inside-out using mild detergent.

Do not use bleach. Dry at a normal dryer setting on household machines. Do not dry clean.

### Storage

Store in a cool and dry area around 65 to 70 degrees Fahrenheit with 50% relative humidity. Keep away from direct heat, sunlight and humidity. Recommended shelf life is one year.

### **Material/Fabric Compatibility**

- 100% Cotton
- 100% Polyester
- Cotton/Poly Blends
- Lycra®/Spandex Blends

### **Note**

The recommended time, temperature, and pressure settings are for Stahls' Hotronix® heat press machines. Settings on other heat presses may vary.